


Monitor® WELL CAPS

Vermin Proof Aluminum Well Cap Instruction Sheet
Code approved in Wisconsin, Minnesota, Illinois, Michigan & Iowa



QUALITY FEATURES:

- All ground screw and bolts are stainless steel, will not corrode.
- 3/8" Tenzalloy alloy anchor ring for added strength.
- Custom Cap personalization available.
- Molded Kroyton "G" 3/16" gasket for all season flexibility.

INSTRUCTIONS:

1. Place anchor ring approximately 5/8" over well casing and tighten (3) bolts
2. Place gasket over well casing and align with anchor ring.
3. Place wire guard over casing and insert electrical ground screw.
4. Loosely attach cover plate to anchor ring with (5) bolts
5. To properly seal casing, loosen anchor ring bolts and tighten cover plate bolts evenly.
6. Retighten anchor ring bolts.

Model No.			4WTVA	4.5WTVA	5WTVA	5.5WTVA	6WTVA
Item No.	Description	Qty	Order #	Order #	Order #	Order #	Order #
1	Cover Plate	1	AC4	AC5	AC5.5	AC6	AC7
2	Gasket	1	AG4	AG4.5	AG5.5	AG6	AG7
3	Anchor Ring	1	AR4	AR4.5	AR5	AR5.5	AR6
4	Bolt Kit	1	AB4	AB4.5	AB5	AB5.5	AB6

Model No.			7WTVA	7.5WTVA	8WTVA	10WTVA	12WTVA
Item No.	Description	Qty	Order #	Order #	Order #	Order #	Order #
1	Cover Plate	1	AC7	AC7.5	AC8	AC10	AC12
2	Gasket	1	AG7	AG7.5	AG8	AG10	AG12
3	Anchor Ring	1	AR7	AR7.5	AR8	AR10	AR12
4	Bolt Kit	1	AB7	AB7.5	AB8	AB10	AB12

